




How to Fix Keurig K75 Platinum Brewing System Water Pump Leak

This guide will show you how to fix internal water leaks for the Keurig B70 Platinum Brewing System.

Written By: Kristen Temnyk



INTRODUCTION

Water leaks for the Keurig B70 Brewing System are sometimes caused by an internal disconnection of the water pump and reservoir. Use this guide to open the Keurig and reseal the water pump.




TOOLS:

- [Phillips #2 Screwdriver](#) (1)
 - [Spudger](#) (1)
-





- Move the brewer so that the metal baseplate is easily accessible.
- Remove the five silver 4 mm Phillips #2 screws from the baseplate.

Step 2




- Using a spudger, gently pry the metal baseplate from the brewer.
- Gently set down the baseplate.

Step 3 — How to Fix Keurig K75 Platinum Brewing System Water Pump Leak



- Remove the two silver 4mm Phillips #2 screws that hold the water pump in place.

Step 4



- Realign the rubber gasket of the water pump to create a tight fit.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-10 08:49:56 AM.